



IPC/WHMA-A-620C



Requirements and Acceptance for Cable and Wire Harness Assemblies

If a conflict occurs between the English and translated versions of this document, the English version will take precedence.

Developed by the IPC Task Group (7-31f) of the Product Assurance Subcommittee (7-30) and the WHMA Industry Technical Guidelines Committee (ITGC)

Supersedes:

IPC/WHMA-A-620B with
Amendment 1 -
August 2013
IPC/WHMA-A-620B -
October 2012
IPC/WHMA-A-620A -
July 2006
IPC/WHMA-A-620 -
January 2002

Users of this publication are encouraged to participate in the development of future revisions.

Contact:

IPC

Wiring Harness Manufacturers Assoc.

Table of Contents

<p>1 General 1-1</p> <p>1.1 Scope 1-2</p> <p>1.2 Purpose 1-2</p> <p>1.3 Classification 1-2</p> <p>1.4 Measurement Units and Applications 1-2</p> <p>1.4.1 Verification of Dimensions 1-2</p> <p>1.5 Definition of Requirements 1-2</p> <p>1.5.1 Inspection Conditions 1-3</p> <p>1.5.1.1 Target 1-3</p> <p>1.5.1.2 Acceptable 1-3</p> <p>1.5.1.3 Defect 1-3</p> <p>1.5.1.3.1 Disposition 1-3</p> <p>1.5.1.4 Process Indicator 1-3</p> <p>1.5.1.5 Combined Conditions 1-4</p> <p>1.5.1.6 Conditions Not Specified 1-4</p> <p>1.5.1.7 Uncommon or Specialized Designs 1-4</p> <p>1.5.2 Material and Process Nonconformance 1-4</p> <p>1.6 Process Control 1-4</p> <p>1.6.1 Statistical Process Control 1-5</p> <p>1.7 Order of Precedence 1-5</p> <p>1.7.1 Clause References 1-5</p> <p>1.7.2 Appendices 1-5</p> <p>1.8 Terms and Definitions 1-5</p> <p>1.8.1 FOD (Foreign Object Debris) 1-5</p> <p>1.8.2 Inspection 1-5</p> <p>1.8.3 Manufacturer (Assembler) 1-5</p> <p>1.8.4 Objective Evidence 1-5</p> <p>1.8.5 Process Control 1-5</p> <p>1.8.6 Supplier 1-6</p> <p>1.8.7 User 1-6</p> <p>1.8.8 Wire Diameter (D) 1-6</p> <p>1.9 Requirements Flowdown 1-6</p> <p>1.10 Personnel Proficiency 1-6</p> <p>1.11 Acceptance Requirements 1-6</p> <p>1.12 Inspection Methodology 1-6</p> <p>1.12.1 Process Verification Inspection 1-6</p> <p>1.12.2 Visual Inspection 1-6</p> <p>1.12.2.1 Lighting 1-6</p> <p>1.12.2.2 Magnification Aids 1-6</p> <p>1.12.2.3 Sampling 1-7</p>	<p>1.13 Facilities 1-7</p> <p>1.13.1 Field Assembly Operations 1-7</p> <p>1.13.2 Health and Safety 1-7</p> <p>1.14 Electrostatic Discharge (ESD) Protection 1-7</p> <p>1.15 Tools and Equipment 1-8</p> <p>1.15.1 Control 1-8</p> <p>1.15.2 Calibration 1-8</p> <p>1.16 Materials and Processes 1-8</p> <p>1.17 Electrical Clearance 1-9</p> <p>1.18 Contamination 1-9</p> <p>1.19 Rework/Repair 1-9</p> <p>1.19.1 Rework 1-9</p> <p>1.19.2 Repair 1-9</p> <p>1.19.3 Post Rework/Repair Cleaning 1-9</p> <p>2 Applicable Documents 2-1</p> <p>2.1 IPC 2-1</p> <p>2.2 Joint Industry Standards 2-1</p> <p>2.3 Society of Automotive Engineers (SAE) 2-1</p> <p>2.4 American National Standards Institute (ANSI) 2-1</p> <p>2.5 International Organization for Standardization (ISO) 2-1</p> <p>2.6 ESD Association (ESDA) 2-2</p> <p>2.7 United States Department of Defense (DoD) 2-2</p> <p>2.8 International Electrotechnical Commission (IEC) 2-2</p> <p>2.9 Aerospace Industries Association (AIA/NAS) 2-2</p> <p>2.10 Electronics Industries Alliance 2-2</p> <p>2.11 ASTM International 2-2</p> <p>2.12 Institute of Electrical and Electronics Engineers 2-2</p> <p>3 Preparation 3-1</p> <p>3.1 Stripping 3-2</p> <p>3.2 Strand Damage and End Cuts 3-2</p> <p>3.3 Conductor Deformation/Birdcaging 3-5</p>
--	--

Table of Contents (cont.)

3.4 Twisting of Wires	3-7	4.8.3.2 Solder	4-34
3.5 Insulation Damage – Stripping	3-8	4.8.4 Pierced/Perforated/Punched	4-35
4 Soldered Terminations	4-1	4.8.4.1 Lead/Wire Placement	4-35
4.1 Material, Components and Equipment	4-2	4.8.4.2 Solder	4-37
4.1.1 Materials	4-2	4.8.5 Hook	4-38
4.1.1.1 Solder	4-2	4.8.5.1 Lead/Wire Placement	4-38
4.1.1.1.1 Solder Purity Maintenance	4-3	4.8.5.2 Solder	4-39
4.1.1.2 Flux	4-4	4.8.6 Cup	4-41
4.1.1.3 Adhesives	4-4	4.8.6.1 Lead/Wire Placement	4-41
4.1.1.4 Solderability	4-5	4.8.6.2 Solder	4-42
4.1.1.5 Tools and Equipment	4-5	4.8.7 Series Connected	4-45
4.1.2 Gold Removal	4-5	4.8.8 Lead/Wire Placement – AWG 30 and Smaller Diameter Wires	4-46
4.2 Cleanliness	4-6	5 Crimp Terminations (Contacts and Lugs)	5-1
4.2.1 Presoldering	4-6	5.1 Stamped and Formed – Open Barrel	5-3
4.2.2 Postsoldering	4-6	5.1.1 Insulation Support	5-4
4.2.2.1 Foreign Object Debris (FOD)	4-6	5.1.1.1 Inspection Window	5-4
4.2.2.2 Flux Residue	4-7	5.1.1.2 Crimp	5-6
4.2.2.2.1 Cleaning Required	4-7	5.1.2 Insulation Clearance if No Support Crimp	5-8
4.2.2.2.2 No-Clean Process	4-7	5.1.3 Conductor Crimp	5-9
4.3 Solder Connection	4-8	5.1.4 Crimp Bellmouth	5-11
4.3.1 General Requirements	4-10	5.1.5 Conductor Brush	5-13
4.3.2 Soldering Anomalies	4-11	5.1.6 Carrier Cutoff Tab	5-15
4.3.2.1 Exposed Basis Metal	4-11	5.1.7 Individual Wire Seal	5-16
4.3.2.2 Partially Visible or Hidden Solder Connections	4-11	5.2 Stamped and Formed – Closed Barrel	5-18
4.4 Wire/Lead Preparation, Tinning	4-12	5.2.1 Insulation Clearance	5-19
4.5 Wire Insulation	4-14	5.2.2 Insulation Support Crimp	5-19
4.5.1 Clearance	4-14	5.2.3 Conductor Crimp and Bellmouth	5-21
4.5.2 Postsolder Damage	4-16	5.3 Machined Contacts	5-23
4.6 Insulation Sleeving	4-17	5.3.1 Insulation Clearance	5-23
4.7 Birdcaged Wire (Soldered)	4-19	5.3.2 Insulation Support Style	5-26
4.8 Terminals	4-20	5.3.3 Conductor	5-27
4.8.1 Turrets and Straight Pins	4-23	5.3.4 Crimping	5-29
4.8.1.1 Lead/Wire Placement	4-23	5.3.5 CMA Buildup	5-31
4.8.1.2 Solder	4-25	5.4 Termination Ferrule Crimp	5-33
4.8.2 Bifurcated	4-26	5.5 Shrink Sleeving – Wire Support – Crimped Terminals	5-35
4.8.2.1 Lead/Wire Placement – Side Route	4-26	6 Insulation Displacement Connection (IDC)	6-1
4.8.2.2 Lead/Wire Placement – Bottom and Top Route	4-28	6.1 Mass Termination, Flat Cable	6-2
4.8.2.3 Lead/Wire Placement – Staked/ Constrained Wires	4-30	6.1.1 End Cutting	6-2
4.8.2.4 Solder	4-31	6.1.2 Notching	6-3
4.8.3 Slotted	4-33	6.1.3 Planar Ground Plane Removal	6-4
4.8.3.1 Lead/Wire Placement	4-33	6.1.4 Connector Position	6-5
		6.1.5 Connector Skew & Lateral Position	6-8
		6.1.6 Retention	6-9

Table of Contents (cont.)

6.2 Discrete Wire Termination	6-10	9.3.2 Bonding	9-11
6.2.1 General	6-10	9.4 Connector Damage	9-15
6.2.2 Position of Wire	6-11	9.4.1 Criteria	9-15
6.2.3 Overhang (Extension)	6-12	9.4.2 Limits – Hard Face – Mating Surface	9-16
6.2.4 Insulation Crimp	6-13	9.4.3 Limits – Soft Face – Mating Surface or Rear Seal Area	9-17
6.2.5 Damage in Connection Area	6-15	9.4.4 Contacts	9-18
6.2.6 End Connectors	6-16	9.5 Installation of Contacts and Sealing Plugs into Connectors	9-19
6.2.7 Pass Through Connectors	6-17	9.5.1 Installation of Contacts	9-19
6.2.8 Wiremount Connectors	6-18	9.5.2 Installation of Sealing Plugs	9-21
6.2.9 Subminiature D-Connector (Series Bus Connector)	6-19	10 Over-Molding/Potting	10-1
6.2.10 Modular Connectors (RJ Type)	6-21	10.1 Over-Molding	10-4
7 Ultrasonic Welding	7-1	10.1.1 Mold Fill	10-4
7.1 Insulation Clearance	7-2	10.1.1.1 Inner	10-4
7.2 Weld Nugget	7-3	10.1.1.2 Outer	10-7
8 Splices	8-1	10.1.1.2.1 Mismatch	10-10
8.1 Soldered Splices	8-2	10.1.1.2.2 Fit	10-11
8.1.1 Mesh	8-3	10.1.1.2.3 Cracks, Flow Lines, Chill Marks (Knit Lines) or Weld Lines	10-14
8.1.2 Wrap	8-5	10.1.1.2.4 Color	10-16
8.1.3 Hook	8-7	10.1.2 Blow Through	10-17
8.1.4 Lap	8-8	10.1.3 Position	10-18
8.1.4.1 Two or More Conductors	8-9	10.1.4 Flashing	10-21
8.1.4.2 Insulation Opening (Window)	8-12	10.1.5 Wire Insulation, Jacket or Sleeving Damage	10-23
8.1.5 Heat Shrinkable Solder Devices	8-13	10.1.6 Curing	10-24
8.2 Crimped Splices	8-15	10.2 Potting (Thermoset Molding)	10-25
8.2.1 Barrel	8-15	10.2.1 Filling	10-25
8.2.2 Double Sided	8-18	10.2.2 Fit to Wire or Cable	10-29
8.2.3 Contact	8-21	10.2.3 Curing	10-31
8.2.4 Wire In-Line Junction Devices (Jiffy Junctions) .	8-24	11 Measuring Cable Assemblies and Wires	11-1
8.3 Ultrasonic Weld Splices	8-25	11.1 Measuring – Cable and Wire Length Tolerance	11-2
9 Connectorization	9-1	11.2 Measuring – Cable	11-2
9.1 Hardware Mounting	9-2	11.2.1 Reference Surfaces – Straight/Axial Connectors	11-2
9.1.1 Jackpost – Height	9-2	11.2.2 Reference Surfaces – Right-Angle Connectors	11-3
9.1.2 Jackscrews – Protrusion	9-3	11.2.3 Length	11-3
9.1.3 Retaining Clips	9-4	11.2.4 Breakout	11-4
9.1.4 Connector Alignment	9-5	11.2.4.1 Breakout Measurement Points	11-4
9.2 Strain Relief	9-6	11.2.4.2 Breakout Length	11-5
9.2.1 Clamp Fit	9-6	11.3 Measuring – Wire	11-6
9.2.2 Wire Dress	9-7	11.3.1 Electrical Terminal Reference Location	11-6
9.2.2.1 Straight Approach	9-8	11.3.2 Length	11-7
9.2.2.2 Side Approach	9-9		
9.3 Sleeving and Boots	9-10		
9.3.1 Position	9-10		

Table of Contents (cont.)

12 Marking/Labeling	12-1	13.10.2.1 Solid	13-27
12.1 Content	12-2	13.10.2.2 Conformable Cable	13-29
12.2 Legibility	12-2	13.10.3 Dielectric Cutoff	13-30
12.3 Permanency	12-4	13.10.4 Dielectric Cleanliness	13-32
12.4 Location and Orientation	12-5	13.10.5 Center Conductor Pin	13-33
12.5 Functionality	12-6	13.10.5.1 Point	13-33
12.6 Marker Sleeve	12-7	13.10.5.2 Damage	13-35
12.6.1 Wrap Around	12-7	13.10.6 Solder	13-36
12.6.2 Tubular	12-9	13.11 Swage-Type Connector	13-38
12.7 Flag Markers	12-10	13.12 Soldering and Stripping of Biaxial/ Multi-Axial Shielded Wire	13-39
12.7.1 Adhesive	12-10	13.12.1 Jacket and Tip Installation	13-39
12.8 Tie Wrap Markers	12-10	13.12.2 Ring Installation	13-41
13 Coaxial and Biaxial Cable Assemblies	13-1	14 Securing	14-1
13.1 Stripping	13-2	14.1 Tie Wrap/Lacing Application	14-2
13.2 Center Conductor Termination	13-4	14.1.1 Tightness	14-6
13.2.1 Crimp	13-4	14.1.2 Damage	14-7
13.2.2 Solder	13-6	14.1.3 Spacing	14-8
13.3 Solder Ferrule Pins	13-8	14.2 Breakouts	14-9
13.3.1 General	13-8	14.2.1 Individual Wires	14-9
13.3.2 Insulation	13-10	14.2.2 Spacing	14-10
13.4 Coaxial Connector – Printed Wire Board Mount	13-11	14.3 Routing	14-13
13.5 Coaxial Connector – Center Conductor Length – Right Angle Connector	13-12	14.3.1 Wire Crossover	14-13
13.6 Coaxial Connector – Center Conductor Solder	13-14	14.3.2 Bend Radius	14-14
13.7 Coaxial Connector – Terminal Cover	13-16	14.3.3 Coaxial Cable	14-15
13.7.1 Soldering	13-16	14.3.4 Unused Wire Termination	14-16
13.7.2 Press Fit	13-17	14.3.4.1 Shrink Sleeving	14-16
13.8 Shield Termination	13-18	14.3.4.2 Flexible Sleeving	14-17
13.8.1 Clamped Ground Rings	13-18	14.3.5 Ties over Splices and Ferrules	14-17
13.8.2 Crimped Ferrule	13-19	14.4 Broom Stitching	14-18
13.9 Center Pin	13-21	15 Harness/Cable Electrical Shielding	15-1
13.9.1 Position	13-21	15.1 Braided	15-2
13.9.2 Damage	13-22	15.1.1 Direct Applied	15-3
13.10 Semirigid Coax	13-23	15.1.2 Prewoven	15-5
13.10.1 Bending and Deformation	13-24	15.2 Shield Termination	15-6
13.10.2 Surface Condition	13-27	15.2.1 Shield Jumper Wire	15-6
		15.2.1.1 Attached Lead	15-6
		15.2.1.1.1 Solder	15-7
		15.2.1.1.2 Crimp	15-11
		15.2.1.2 Shield Braid	15-12
		15.2.1.2.1 Woven	15-12
		15.2.1.2.2 Combed and Twisted	15-12
		15.2.1.3 Daisy Chain	15-13
		15.2.1.4 Common Ground Point	15-13

Table of Contents (cont.)

15.2.2	No Shield Jumper Wire	15-14	17.3.7.1	Wire/Cable Bundle Sealing Not Required	17-19
15.2.2.1	Shield Not Folded Back	15-14	17.3.7.1.1	Wire/Cable Sealing Required	17-20
15.2.2.2	Shield Folded Back	15-15			
15.3	Shield Termination – Connector	15-16	18	Solderless Wrap	18-1
15.3.1	Shrink	15-16	18.1	Number of Turns	18-2
15.3.2	Crimp	15-18	18.2	Turn Spacing	18-3
15.3.3	Shield Jumper Wire Attachment	15-20	18.3	End Tails, Insulation Wrap	18-4
15.3.4	Soldered	15-21	18.4	Raised Turns Overlap	18-6
15.4	Shield Termination – Splicing Prewoven	15-21	18.5	Connection Position	18-7
15.4.1	Soldered	15-21	18.6	Wire Dress	18-9
15.4.2	Tie/Tape On	15-23	18.7	Wire Slack	18-10
15.5	Tapes – Barrier and Conductive, Adhesive or Nonadhesive	15-24	18.8	Plating	18-11
15.6	Conduit (Shielding)	15-25	18.9	Damage	18-12
15.7	Shrink Tubing – Conductive Lined	15-26	18.9.1	Insulation	18-12
16	Cable/Wire Harness Protective Coverings	16-1	18.9.2	Wires and Terminals	18-13
16.1	Braid	16-2	19	Testing	19-1
16.1.1	Direct Applied	16-2	19.1	Nondestructive Tests	19-2
16.1.2	Prewoven	16-4	19.2	Testing After Rework or Repair	19-2
16.2	Sleeving/Shrink Tubing	16-6	19.3	Intended Table Usage	19-2
16.2.1	Sealant	16-7	19.4	Electrical Test	19-3
16.3	Spiral Plastic Wrap (Spiral Wrap Sleeving)	16-8	19.4.1	Selection	19-3
16.4	Wire Loom Tubing – Split and Unsplit	16-9	19.5	Electrical Test Methods	19-4
16.5	Tapes, Adhesive and Nonadhesive	16-9	19.5.1	Continuity	19-4
17	Finished Assembly Installation	17-1	19.5.2	Shorts	19-5
17.1	General	17-2	19.5.3	Dielectric Withstanding Voltage (DWW)	19-6
17.2	Hardware Installation	17-3	19.5.4	Insulation Resistance (IR)	19-7
17.2.1	Threaded Fasteners	17-4	19.5.5	Voltage Standing Wave Ratio (VSWR)	19-8
17.2.1.1	Minimum Torque	17-6	19.5.6	Insertion Loss	19-8
17.2.2	Wires	17-8	19.5.7	Reflection Coefficient	19-9
17.2.3	Safety Wiring	17-11	19.5.8	User Defined	19-9
17.2.4	Safety Cable	17-13	19.6	Mechanical Test	19-10
17.3	Wire/Harness Installation	17-14	19.6.1	Selection	19-10
17.3.1	Stress Relief	17-14	19.7	Mechanical Test Methods	19-11
17.3.2	Wire Dress	17-15	19.7.1	Crimp Height (Dimensional Analysis)	19-11
17.3.3	Service Loops	17-16	19.7.1.1	Terminal Positioning	19-12
17.3.4	Clamping	17-17	19.7.2	Pull Force (Tensile)	19-13
17.3.5	Tie Wrap Lacing	17-17	19.7.2.1	Without Documented Process Control	19-14
17.3.6	Raceways	17-18	19.7.3	Crimp Force Monitoring	19-18
17.3.7	Grommets	17-19	19.7.4	Crimp Tool Qualification	19-18

Table of Contents (cont.)

19.7.5	Contact Retention Verification	19-18	Table 13-1	Coaxial and Biaxial Shield and Center Conductor Damage	13-2
19.7.6	RF Connector Shield Pull Force (Tensile) ...	19-19	Table 13-2	Semirigid Coax Deformation	13-25
19.7.7	RF Connector Shield Ferrule Torsion	19-20	Table 13-3	Dielectric Cutoff	13-30
19.7.8	User Defined	19-20	Table 14-1	Minimum Bend Radius Requirements	14-14
20	High Voltage Applications	20-1	Table 17-1	Minimum Swaged Ferrule Pull-Off Load	17-13
Appendix A	Terms and Definitions	A-1	Table 18-1	Minimum Turns of Bare Wire	18-2
Appendix B	Reproducible Test Tables	B-1	Table 19-1	Electrical Test Requirements	19-3
Appendix C	Guidelines for Soldering Tools and Equipment	C-1	Table 19-2	Continuity Test Minimum Requirements	19-4
Table A-1	Electrical Clearance	A-5	Table 19-3	Shorts Test (low voltage isolation) Minimum Requirements	19-5
Table 1-1	Magnification Aids	1-7	Table 19-4	Dielectric Withstanding Voltage Test (DWV) Minimum Requirements ...	19-6
Table 1-2	Magnification Aid Applications – Other	1-7	Table 19-5	Insulation Resistance (IR) Test Minimum Requirements	19-7
Table 3-1	Allowable Strand Damage	3-4	Table 19-6	Voltage Standing Wave Ratio (VSWR) Test Parameters	19-8
Table 4-1	Maximum Limits of Solder Bath Contaminant	4-3	Table 19-7	Insertion Loss Test Parameters	19-8
Table 4-2	Solder Connection Anomalies	4-11	Table 19-8	Reflection Coefficient Test Parameters	19-9
Table 4-3	Turret and Straight Pin Terminal Lead/Wire Placement	4-23	Table 19-9	Mechanical Test Requirements	19-10
Table 4-4	Bifurcated Terminal Lead/Wire Placement – Side Route	4-26	Table 19-10	Crimp Height Testing	19-11
Table 4-5	Bifurcated Terminal Lead/Wire Placement – Bottom Route	4-28	Table 19-11	Pull Force Testing Minimum Requirements	19-14
Table 4-6	Staking Requirements of Side Route Straight Through Connections – Bifurcated Terminals	4-30	Table 19-12	Pull Test Force Values	19-15
Table 4-7	Pierced or Perforated Terminal Lead/Wire Placement	4-35	Table 19-13	Pull Test Force Values (Classes 1 & 2) For UL, SAE, GM and Volvo ...	19-16
Table 4-8	Hook Terminal Lead/Wire Placement ...	4-38	Table 19-14	Pull Test Force Values (Classes 1 & 2) For IEC	19-17
Table 4-9	AWG 30 and Smaller Wire Wrap Requirements	4-46	Table 19-15	RF Connector Shield Pull Force Testing	19-19
Table 10-1	Definitions of Molding/Potting Visual Anomalies	10-2			
Table 11-1	Cable/Wire Length Measurement Tolerance	11-2			

1 Requirements and Acceptance for Cable and Wire Harness Assemblies

General

The following topics are addressed in this section:

1 General

1.1 Scope

1.2 Purpose

1.3 Classification

1.4 Measurement Units and Applications

1.4.1 Verification of Dimensions

1.5 Definition of Requirements

1.5.1 Inspection Conditions

1.5.1.1 Target

1.5.1.2 Acceptable

1.5.1.3 Defect

1.5.1.3.1 Disposition

1.5.1.4 Process Indicator

1.5.1.5 Combined Condition

1.5.1.6 Conditions Not Specified

1.5.1.7 Uncommon or Specialized Designs

1.5.2 Material and Process Nonconformance

1.6 Process Control

1.6.1 Statistical Process Control

1.7 Order of Precedence

1.7.1 Clause References

1.7.2 Appendices

1.8 Terms and Definitions

1.8.1 FOD (Foreign Object Debris)

1.8.2 Inspection

1.8.3 Manufacturer (Assembler)

1.8.4 Objective Evidence

1.8.5 Process Control

1.8.6 Supplier

1.8.7 User

1.8.8 Wire Diameter (D)

1.9 Requirements Flowdown

1.10 Personnel Proficiency

1.11 Acceptance Requirements

1.12 Inspection Methodology

1.12.1 Process Verification Inspection

1.12.2 Visual Inspection

1.12.2.1 Lighting

1.12.2.2 Magnification Aids

1.12.2.3 Sampling

1.13 Facilities

1.13.1 Field Assembly Operations

1.13.2 Health and Safety

1.14 Electrostatic Discharge (ESD) Protection

1.15 Tools and Equipment

1.15.1 Control

1.15.2 Calibration

1.16 Materials and Processes

1.17 Electrical Clearance

1.18 Contamination

1.19 Rework/Repair

1.19.1 Rework

1.19.2 Repair

1.19.3 Post Rework/Repair Cleaning

1 Requirements and Acceptance for Cable and Wire Harness Assemblies

General (cont.)

1.1 Scope This standard prescribes practices and requirements for the manufacture of cable, wire and harness assemblies. This standard does not provide criteria for cross-section or X-ray evaluation.

If a conflict occurs between the English and translated versions of this document, the English version will take precedence.

IPC/WHMA-A-620 can be used as a stand-alone document for purchasing products; however it does not specify frequency of in-process inspection or frequency of end product inspection. No limit is placed on the number of process indicators or the number of allowable repair/rework of defects. Such information should be developed with a statistical process control plan (see IPC-9191).

The illustrations in this document portray specific points noted in the title of each section. A brief description follows each illustration. The development committee recognizes that different parts of the industry have different definitions for some terms used herein. For the purposes of this document, the terms cable and wire harness are used interchangeably.

1.2 Purpose This standard describes materials, methods, tests and acceptability criteria for producing crimped, mechanically secured, or soldered interconnections and the related assembly activities associated with cable and harness assemblies.

The intent of this document is to rely on process control methodology to ensure consistent quality levels during the manufacture of products.

Any method that produces an assembly conforming to the acceptability requirements described in this standard may be used.

Standards may be updated at any time, including with the use of amendments. The use of an amendment or newer revision is not automatically required. The revision in effect **shall [D1D2D3]** be as specified by the User.

1.3 Classification Use of this standard requires agreement on the Class to which the product belongs. The User has the ultimate responsibility for identifying the Class to which the assembly is evaluated. If the User does not establish and document the acceptance Class, the Manufacturer may do so. Accept and/or reject decisions **shall [D1D2D3]** be based on applicable documentation such as contracts, drawings, specifications, standards and reference documents. Criteria defined in this standard reflect three Product Classes, which are as follows:

Class 1 General Electronic Products

Includes products suitable for applications where the major requirement is the function of the completed assembly.

Class 2 Dedicated Service Electronic Products

Includes products where continued performance and extended life is required, and for which uninterrupted service is desired but not critical. Typically, the end-use environment would not cause failures.

Class 3 High Performance/Harsh Environment Electronic Products

Includes products where continued performance or performance-on-demand is critical, equipment downtime cannot be tolerated, end-use environment may be uncommonly harsh, and the equipment must function when required, such as life support systems and other critical systems.

1.4 Measurement Units and Applications This document uses the International System of Units (SI) in accordance with ASTM SI10-10, IEEE/ASTM SI 10, American National Standard for Metric Practice (Section 3). Imperial English equivalent units follow in brackets. The derived SI units used in this document are millimeters (mm) [in] for dimensions and dimensional tolerances, Celsius (°C) [°F] for temperature and temperature tolerances, grams (g) [oz] for weight, and lux (lx) [footcandles] for illuminance.

1.4.1 Verification of Dimensions Where not specifically invoked by this standard, actual measurements (e.g. of specific solder fillet dimensions, determination of damage and wrap percentages) are not required except for referee purposes.

1.5 Definition of Requirements The word “**shall**” is used in the text of this document wherever there is a requirement for materials, process or acceptance of cable, wire and harness assemblies.